

# Heat Trace - Accessories


## CONNECTIONS



PART NUMBER: PCA-40J, PCA-40P, \*PCA-81J, \*PCA-81P

DESCRIPTION: Power Connection kit for CRG, LSR, MSR, and HSR heating cable.

\* J denotes kit with Junction Box Included. PCA-81J, PCA-81P for HSR heating cable.



PART NUMBER: HTJB-1

DESCRIPTION: DIN rail junction box for heat trace termination.

\* Pipe stand sold separately (PCA-40P/PCA-81P)



PART NUMBER: ESA-ES, \*ESA-81

DESCRIPTION: End Termination Kit for CRG, LSR, MSR, and HSR heating cable.

\* ESA-81 for HSR



PART NUMBER: LESA-1, LESA-2

DESCRIPTION: End of circuit termination light kit.



PART NUMBER: SPTA-1

DESCRIPTION: Splice/Tee kit for heater cable connection

\* SPTA-1 - contents included for 10 connections

# Heat Trace - Accessories

## INSTALLATION KITS



PART NUMBER: HTRTD-25

DESCRIPTION: Armored RTD cable and cord grip with 25' leads



PART NUMBER: HTPS-6, HTPS-10

DESCRIPTION: Pipe strap for securing connections to pipe.

PART NUMBER: HTFT-1

DESCRIPTION: Application fiberglass tape for securing heat trace to pipe.

PART NUMBER: HTAT-1

DESCRIPTION: Application aluminum tape for securing heat trace to non-metallic pipe.



PART NUMBER: HTFLXCNDT3/4-36

DESCRIPTION: 3 foot flex conduit with 3/4" NPT fittings for power cable entry.



PART NUMBER: HTCL-1

DESCRIPTION: Warning label noting electric heat trace